


Due to the (almost) low power design
and the missing MCP1703 sink capability,
the circuit does not include any
overvoltage protection...
You have been warned!

Inputs are floating.
This is a feature, not a bug ;)



all sizes 0805 except where noted

[illegible]

(c) ASkr
www.askrprojects.net

Sheet: 1/1